



- Pos.: 18.3 - Manhole 840x1440
- Rear wall - 1 pcs.
- Y-50 anchors 25x5 ~ 80 pcs.




REFRACTORY AREA

- Pos.: 18.4 - Recirculation flue gas
Secondary air
- REFRACTORY AREA
- Front wall and Rear wall - 2x10 pcs. + 2x8 pcs.
- Y-45 anchors 25x5 ~4 pcs.



REFRACTORY AREA


- Pos.: 18.6
- REFRACTORY AREA
- Opening for sidewalls bottom header (header welding) - 2 pcs.



Anchors are welded on site


OUTSIDE
REFRACTORY AREA

- Pos.: 18.12 Opening for membrane walls
- OUTSIDE
REFRACTORY AREA
- Roof 2nd. pass - 3 pcs.




Anchors are welded on site

- Pos.: 18.7.1 SNCR level 1 & 2
- REFRACTORY AREA
- Front wall and sidewalls - 8 pcs.
- Y-45 anchors 25x5 ~ 4 pcs.



REFRACTORY AREA


- Pos.: 18.7.2 SNCR level 1 & 2
- REFRACTORY AREA
- Front wall - 4 pcs.
- Y-45 anchors 25x5 ~ 8 pcs.



Anchors are welded on site


REFRACTORY AREA

- Pos.: 18.7.3 Measuring point
- REFRACTORY AREA
- Rear wall - 6 pcs.
- Y-45 anchors 25x5 ~ 6 pcs.



Anchors are welded on site

Anchor material: 253 MA
1.4835



WYMURÓWKA KOTŁA 21

P.U.H.P. „LECH” Sp. z o.o. w Białymstoku
Zakład Unieszkodliwiania Odpadów Komunalnych w Białymstoku